



# Rotator - Bowl - Large

Manufactured by (Unknown)



## Standards:



EN 1176-5:2008, EN 1176-1:2017

The item and its surfacing (where applicable) meet with the requirements of the relevant standards.

## Finding

### Description

Item is rocking.

### Tasks

Repair.

### Note

Central pivot / post is very loose and rocking excessively. The item could collapse on someone.

**Risk level:**

High

**Risk score:**

15

## Finding Photos



## Finding

### Description

Paintwork is in poor condition.

### Tasks

De-scale back to good base material and coat with lead free paint, using appropriate precautions. Repairs may be necessary where corrosion is severe.

Risk level:

 Low

Risk score:

 5

### Finding Photos



## Finding

### Description

The surface is cracking.

### Tasks

No reasonably practicable action is identified.

### Note

Red wet pour.

Risk level:

 Low

Risk score:

 4

### Finding Photos

